





# Harta amenintarilor E 02 Zone industriale

Anexa 2.22.5.



## LEGENDA

-  Cariere exploatare agregate minerale
-  Depozite steril exploatare miniere
-  Areale industriale abandonate ( ruine )